Historic American Engineering Record

INDEX

TO PHOTOGRAPHS

HAER Wash 17-Falciy 1-

Raging River Bridge No. 234A
Preston-Fall City Road and S6 44th A.
Fall City Vicinity
King County
Washington

HAER No. WA-141

John Stamets, Photographer

June, July 1997

HAER No.	Description
WA-141-1	View of east girder spanning river, looking upstream and westward.
WA-141-2	View looking south from sidewalk includes half-through west girder on left and Raging River (upstream) on right.
WA-141-3	West side of bridge, looking SE from bank, shows white concrete sidewalk railing.
WA-141-4	SW corner of bridge shows sidewalk and art deco concrete railing.
WA-141-5	Elevation of east side of south approach.
WA-141-6	Art deco railing detail on SE side. Partial segment in left foreground is same as center segment in photo WA-141-5.
WA-141-7	Rounded south end of west girder and sidewalk.
WA-141-8	View from underneath bridge on west side shows cantilevered steel supports for sidewalk above.
WA-141-9	View from underneath bridge looking north from south bank.
WA-141-10	View of north section of bridge shows east girder as it attaches to north concrete abutment. Note expansion rocker shoe.
WA-141-11	Detail of expansion rocker shoe on base slab in NW corner.
WA-141-12	Detail of fixed shoe in SW corner with concrete pillar in background.